

Cogging Temperature of Tungsten, Molybdenum and Their Alloys

Name	Mark	Standards /mm	Heating Temperature/°C	Heating Time/min
Pure Tungsten	W-1, W-2	10 X 10 X 350	1400 ~ 1500	20 ~ 25
Tungsten Aluminium	WAl	10 X 10 X 350	1450 ~ 1500	20 ~ 25
Tungsten Rhenium	WRe	10 X 10 X 350	1550 ~ 1650	20 ~ 25
Tungsten Cerium	WCe	10 X 10 X 350	1500 ~ 1600	20 ~ 25
Pure Molybdenum	Mo-1, Mo-2	14 x 14 x 500	1400 ~ 1500	20 ~ 25
Molybdenum Tungsten	MoW20	10 X 10 X 350	1500 ~ 1600	20 ~ 25
	MoW50	10 X 10 X 350	1500 ~ 1600	20 ~ 25